METALLIMAX®

Used-up reamers cost you time, effort and quality.

3× EFFORT REQUIRED*

95–318%

Dull reamers require excessive force.[2]

DIAMETRICAL IMPRECISION

−1.33 mm

Dull reamers undersize the cavity.[1]

2× TIME REQUIRED

+100%

Reaming time is doubled with used-up reamers.[2†]

SIGNIFICANT UNDER-REAMING

−3.4 mm

Dull reamers fail to reach the same depth.[2]

THERMAL NECROSIS

65.1 °C

Dull reamers can generate extreme temperatures.[2,3]

VS



±250 µm
TRUE TO SIZE**[5,6]

25%
LESS TORQUE**[4,6]

39%
SMOOTHER BONE FINISH**[5,6]

One ream. To the right size.

Join the OneReam Revolution.

orders@metallimax.com
(772) 265-4681
www.metallimax.com

** Problem data: bench and animal studies of generic new vs used reamers, not OneReam; bone injury seen at 47 °C for 1 min.[3] † Extra time allotted by study protocol, not measured. ** OneReam data: bench test of identical cutting-tooth geometry vs a standard reamer (52 mm, 30 PCF Sawbones); may not predict clinical performance.*

Refs: 1. Slotkin S, et al. *Arthroplasty Today*. 2016;3(2):131–136 · 2. Sherman WF, et al. *Arthroplasty Today*. 2021;7:91–97 · 3. Eriksson AR, Albrektsson T. *J Prosthet Dent*. 1983;50(1):101–107 · 4. Tecomet TS-18-0008, torque/cutting efficiency test · 5. Tecomet TS-18-0010, size, form and smoothness test · 6. Tecomet Cross Bar Reamer Data Sheet 10008-01 Rev. B.

© METALLIMAX, LLC · OneReam is a registered trademark of Metallimax, LLC.